

send_org_id	Minnesota DOT	Minnesota DOT	Minnesota DOT	Minnesota DOT	Minnesota DOT
send_ctr_id	MSP/CAD System	MSP/CAD System	MSP/CAD System	MSP/CAD System	MSP/CAD System
msg_version	1	1	1	1	1
msg_number	1358543272	1358543197	1358547327	1358542508	1358546314
msg_timestamp	2/5/2013 10:01	2/5/2013 9:16	2/12/2013 1:46	2/4/2013 9:46	2/10/2013 20:16
msg_expire_time	11/25/2016 7:06	11/25/2016 6:25	12/1/2016 23:00	11/24/2016 7:00	11/30/2016 17:32
event_id	MSPCAD-P130058434	MSPCAD-P130058366	MSPCAD-P130070244	MSPCAD-P130056879	MSPCAD-P130068439
event_update	4	3	3	2	3
event_status	current	current	current	current	current
event_priority	4	4	4	4	6
headline_text	[3818]crash	[3818]crash	[3818]crash	[3818]crash	[3818]disabled vehicle
d_desc_id	1	1	1	1	1
d_desc_text	[3818]crash	[3818]crash	[3818]crash	[3818]crash	[3818]disabled vehicle
route_designator	I-35	I-35	I-35	I-35	I-35
primary_loc (lat, Lon, Ele)	{44.0297, -93.2466, 37.9583}	{44.0725, -93.2518, 40.8984}	{44.0862, -93.2456, 41.8976}	{44.102, -93.2452, 42.9808}	{44.102, -93.2452, 42.9808}
d_loc_link_dir	negative direction	positive direction	negative direction	positive direction	positive direction
d_loc_link_lref_ver	1	1	1	1	1
update_time	2/5/2013 10:01	2/5/2013 9:16	2/12/2013 1:46	2/4/2013 9:46	2/10/2013 20:16
start_time	2/5/2013 8:53	2/5/2013 8:31	2/12/2013 0:50	2/4/2013 9:24	2/10/2013 19:39
duration_min	1:08:28	0:45:01	0:56:01	0:21:58	0:36:39